

Derating with No Heat Sink for CBS5048 series




fig. 1 Derating with No Heat Sink




fig. 2 Test Method

Note: Verify that baseplate temperature is below design level.